



C/C\$

03500.014507 (35.C14507)

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
SEIJI HASHIMOTO, ET AL.)
Appln. No.: 09/584,198)
Filed: May 31, 2000)
For: IMAGE PICKUP APPARATUS HAVING)
PLURAL PIXELS ARRANGED)
TWO-DimensionALLY, AND SELECTIVE)
ADDITION OF DIFFERENT PIXEL COLOR)
SIGNALS TO CONTROL SPATIAL COLOR)
ARRANGEMENT)

Examiner: Heather R. Long
Group Art Unit: 2615
Patent No.: 6,992,714 B1
Issued: January 31, 2006
June 28, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**Certificate
of Correction**
JUL 03 2006

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

06/29/2006 SZEWDIE1 00000075 6992714

01 FC:1811

100.00 0P

JUL 05 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010. All correspondence should be directed to our address given below.

Respectfully submitted,



Daniel S. Glueck
Attorney for Patentees
Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DSG/ljp

DC_MAIN 243070v1

2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 13, "comprises" should read -- that comprises;--.

Line 42, "aspect" should read --another aspect--.

COLUMN 4

Line 24, "circuit" should read --circuit;--.

Line 26, "circuit" should read --circuit;--.

COLUMN 5

Line 15, "arrangement." should read --arrangement;--.

Line 19, "arrangement." should read --arrangement;--.

Line 55, "in a" should read --in an--.

COLUMN 6

Line 5, "is." should read --is--.

Line 57, "preformed" should read --performed--.

COLUMN 7

Line 5, "Is" should read --is--

Line 52, "is-transferred" should read --is transferred--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lp DC_MAIN 243071

2006 →

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8

Line 1, "above described" should read --above-described--.

Line 40, "all" should read --all--.

Line 49, "common a" should read --common--.

Line 56, "all" should read --all--.

Line 59, "all" should read --all--.

COLUMN 10

Line 25, "memory." should read --memory--.

Line 45, "preformed" should read --performed--.

COLUMN 11

Line 17, "add together" should read --added together--.

Line 60, "C-and" should read --C and--.

COLUMN 12

Line 56, "above described" should read --above-described--.

COLUMN 16

Line 41, "preformed" should read --performed--.

Line 44, "EL" should read --SEL--.

COLUMN 18

Line 43, "gates,." should read --gates,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page



2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 20, "scanning m" should read --scanning--.

COLUMN 22

Line 24, "in is" should read --is--.

Line 39, "all" should read --a l l--.

Line 59, "rest" should read --reset--.

COLUMN 23

Line 12, "rest" should read --reset--.

Line 51, "ϕRES" should read --ϕMRES--.

COLUMN 25

Line 10, "amy" should read --may--.

COLUMN 26

Line 17, "more." should read --more--.

Line 24, "a the" should read --the--.

Line 56, "all" should read --a l l--.

COLUMN 27

Line 1, "all" should read --a l l--.

Line 22, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lp DC_MAIN 243071



05 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 28

Line 7, "are." should read --are--.

Line 54, "above described" should read --above-described--.

Line 58, "arrangement" should read --arrangements--.

COLUMN 30

Line 9, "two-dimensionally:" should read --two-dimensionally;--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lp DC_MAIN 243071

30 MAY 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 13, "comprises" should read -- that comprises:--.

Line 42, "aspect" should read --another aspect--.

COLUMN 4

Line 24, "circuit" should read --circuit;--.

Line 26, "circuit" should read --circuit;--.

COLUMN 5

Line 15, "arrangement." should read --arrangement;--.

Line 19, "arrangement." should read --arrangement;--.

Line 55, "in a" should read --in an--.

COLUMN 6

Line 5, "is." should read --is--.

Line 57, "preformed" should read --performed--.

COLUMN 7

Line 5, "Is" should read --is--

Line 52, "is-transferred" should read --is transferred--.

Staple
Here
Only!

PRINTER'S TRIM LINE

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/ltp DC_MAIN 243071

JAN 05 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8

Line 1, "above described" should read --above-described--.

Line 40, "all" should read --all--.

Line 49, "common a" should read --common--.

Line 56, "all" should read --all--.

Line 59, "all" should read --all--.

COLUMN 10

Line 25, "memory." should read --memory--.

Line 45, "preformed" should read --performed--.

COLUMN 11

Line 17, "add together" should read --added together--.

Line 60, "C-and" should read --C and--.

COLUMN 12

Line 56, "above described" should read --above-described--.

COLUMN 16

Line 41, "preformed" should read --performed--.

Line 44, "EL" should read --SEL--.

COLUMN 18

Line 43, "gates,." should read --gates,--.

Staple
Here
Only!

PRINTER'S TRIM LINE

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 243071

05 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19

Line 20, "scanning m" should read --scanning--.

COLUMN 22

Line 24, "in is" should read --is--.

Line 39, "all" should read --all--.

Line 59, "rest" should read --reset--.

COLUMN 23

Line 12, "rest" should read --reset--.

Line 51, "RES" should read --MRES--.

COLUMN 25

Line 10, "amy" should read --may--.

COLUMN 26

Line 17, "more." should read --more--.

Line 24, "a the" should read --the--.

Line 56, "all" should read --all--.

COLUMN 27

Line 1, "all" should read --all--.

Line 22, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 243071



2006 05 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,992,714 B1

DATED : January 31, 2006

INVENTOR(S) : Seiji Hashimoto, et al.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 28

Line 7, "are." should read --are--.

Line 54, "above described" should read --above-described--.

Line 58, "arrangement" should read --arrangements--.

COLUMN 30

Line 9, "two-dimensionally:" should read --two-dimensionally;--.

Staple
Here
Only!

PRINTER'S TRIM LINE

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,992,714 B1

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lp DC_MAIN 243071

6,992,714 B1

